



Atletska zveza Slovenije | Letališka cesta 33c | 1122 Ljubljana  
T 01 520 69 12 | F 01 520 69 16  
E [info@atletska-zveza.si](mailto:info@atletska-zveza.si) | [www.slovenska-atletika.si](http://www.slovenska-atletika.si)

**ATLETSKA  
ZVEZA  
SLOVENIJE**

# **TRACK AND FIELD FACILITIES IN SLOVENIA**

Authors: Gabrijel Ambrožič and Zdravko Peternelj

Ljubljana, July 2016

# LJUBLJANA

## GENERAL INFORMATION:

**Venue name:** Park Šiška

**Operator:** Javni Zavod Šport Ljubljana

**Built:** 1986, renovated in 1998/99

**Capacity:** 1850 seated covered and 450 seated uncovered, 900 standing

**Certification:** 2006, 2009, 2014

## FACILITY:

Surface: polytan Retopping SE, 8.000 m<sup>2</sup>

- 8 lines / 400m
- 2x: long jump, triple jump, high jump, pole vault
- 1x: shot put, discus, hammer, javelin

## FACILITY CONDITION – shortcomings:

- intrusion of running track about 10-12 cm deep in length about 15 m on the east side of the stadium;
- worn out synthetic surface, cracked at several points at intersections and at curbs and deviates from asphalt substrate;
- extremely hard synthetic surface, unsuitable for training and competitions;
- the synthetic surface at the jump site with the rod deviates from the asphalt surface;
- damaged inner plastic edges (broken, improperly laid) on both semicircles;
- worn out and cracked synthetic surface in the hall below the podium. The roof of the hall allows water;
- the protection structure with a hammer net does not comply with the rules;
- ground electrical and electronic connections are in poor condition;
- incomplete manual scoreboards (missing numbers);
- the level of the sand is too low in all areas;

## EQUIPMENT CONDITION – what is missing?

- the equipment in the gym is in poor condition
- Damaged hurdles
- high jump mat covers are in poor condition
- a large number of high jump/pole vaults bars have wrong ends

## OBJECTIVES

The priorities are as follows:

- construction of a training competition hall with a 200 m circular track
- general restoration of synthetic surface and electrical connections
- repairing the rooftop or constructing a new common rostrum
- arrangement of the protective construction of the hammer and the discus
- renewal of the pole vault site

Transfer of ownership between Slovenian Railways and the City of Ljubljana is underway.

**SUITABLE FOR RANK OF COMPETITIONS:**

- all competitions

**OBJECT RANK: A**



# LJUBLJANA

## GENERAL INFORMATION:

**Venue name:** auxiliary stadium Ljubljana

**Operator:** Javni Zavod Šport Ljubljana

**Built:** 1996

**Capacity:** 500 standing

**Certification:** 2009, 2014

## FACILITY:

Surface: polytan S, 6.010 m<sup>2</sup>

- 6 lines / 400m
- 1x: long jump, triple jump, high jump, pole vault
- 1x: discus
- 2x: shot put, hammer, javelin

## FACILITY CONDITION – shortcomings:

- worn out synthetic surface, cracked at several points at intersections and at curbs and deviates from asphalt substrate;
- raised synthetic cover on the sixth track due to the overgrown roots on the north side of the stadium
- damaged inner plastic edges; grass grows on the inside and outside of the curbs
- no water jump for steeple chase
- no electrical or electronic floor connections
- no conditions for electronic time measurements
- facility for hammer throw B is adjacent to the auxiliary stadium and is incorrectly located
- long jump and triple jump facility is useless
- trees to be removed in the extension of the long jump landing area on the north side of the stadium
- level of sand is too low in all landing areas
- segment spear line at 70 m comes on the embankment

## EQUIPMENT CONDITION – what is missing?

- take-off boards with plasticine sheets are completely worn out
- high jump mat covers are in bad condition
- a large number of high jump/pole vaults bars have wrong ends

## OBJECTIVES

The priorities are as follows:

- arrangement of all facilities
- move the B throwing site to javelin throwing site
- construction of a steeple chase water jump barrier
- relocation of the protective structure on the triangle and removal of stones in the throwing sector
- Arrangement of an auxiliary training and competition stadium is a condition for the subsequent renovation of the main athletic facility and the construction of a circular athletic hall.

**SUITABLE FOR RANK OF COMPETITIONS:**

- national championships U12, U14, U16
- school competitions
- meetings

**OBJECT RANK: C**



# MARIBOR

## GENERAL INFORMATION:

**Venue name:** Poljane stadium

**Operator:** Železničarsko športno društvo Maribor

**Built:** 1976, renovated 1997, partly renovated 2008

**Capacity:** 60 seated, 1500 standing

**Certification:** 2009, 2014

## FACILITY:

Surface: polytan SE Retopping, 6.481 m<sup>2</sup>

- 8 lines / 400m
- 2x: long jump, triple jump, high jump,
- 1x: pole vault
- 2x: shot put
- 1x: discus, hammer, javelin

## FACILITY CONDITION – shortcomings:

- the opening of the protective structure does not meet the Rules for competitions
- the inner curb is not positioned on both semicircles of the stadium
- there are no starting points and obstacles marks on the inner curb in the final straight
- the curbs at the long jump runway are cracked in several places
- high jump and pole vault facilities are worn out

## EQUIPMENT CONDITION – what is missing?

- start cart
- platoon for placement of target video camera is not in accordance with the rules (minimum prescribed angle is not reached)

## OBJECTIVES

The priorities are as follows:

- construction of a new grandstand and indoor hall with 6 lanes and facilities for long jumps and high jumps
- new offices as part of a new grandstand construction
- purchase of a high jump equipment
- purchase of pole vault equipment
- sound system installation
- purchase two manual scoreboards

## SUITABLE FOR RANK OF COMPETITIONS:

- all competitions

## OBJECT RANK: A





# CELJE

## GENERAL INFORMATION:

**Venue name:** Kladivar athletic stadium

**Operator:** AD Kladivar Celje

**Built:** 1970, renovated 1996

**Capacity:** 1500 seated, 1000 standing

**Certification:** 2006, 2009, 2014

## FACILITY:

Surface: polytan M, 7.336 m<sup>2</sup>

- 8 lines / 400m
- 1x: long jump, triple jump, high jump, pole vault
- 1x: shot put, discus, hammer, javelin

## FACILITY CONDITION – shortcomings:

- worn out synthetic surface
- poorly visible floor markings
- no electrical connections
- shot put sector too high

## EQUIPMENT CONDITION – what is missing?

- high jump mats are in bad condition
- worn out high jump stands

## OBJECTIVES

The priorities are as follows:

- general renovation of synthetic surface and floor markings
- purchase of high jump mats and stands
- to arrange better conditions for the work of the measuring team

## SUITABLE FOR RANK OF COMPETITIONS:

- all competitions

## OBJECT RANK: A





# KOPER

## GENERAL INFORMATION:

**Venue name:** Sport Park Bonifika Koper

**Operator:** Javni zavod za šport Koper

**Built:** 2010

**Capacity:** 500 seated

**Certification:** 2011, 2014

## FACILITY:

Surface: polytan, 6.792 m<sup>2</sup>

- 8 lines / 400m
- 1x: long jump, triple jump, high jump, pole vault
- 1x: shot put, discus, hammer
- 2x: javelin

## FACILITY CONDITION:

- new venue which is IAAF rules compliant
- venue is IAAF certified (rank 2)

## EQUIPMENT CONDITION – what is missing?

- renovation of high jump and pole vault facility
- there are no marks at long jump/triple jump landing areas
- the right door carrier of the protective structure is not in the proper position
- water jump barrier is not stable

## OBJECTIVES

The priorities are as follows:

- to build an auxiliary hammer and discus throw site

## SUITABLE FOR RANK OF COMPETITIONS:

- all competitions

**OBJECT RANK: A** (after meeting the requirements of the certificate)





# KRANJ

## GENERAL INFORMATION:

**Venue name:** Sport center Kranj

**Operator:** Zavod za šport Kranj

**Built:** 1986, renovated in two stages in 1998 and 1999

**Capacity:** 2160 seated, 1000 standing

**Certification:** 2009, 2014

## FACILITY:

Surface: polytan M, 5.900 m<sup>2</sup>

- 8 lines / 400m
- 1x: long jump, triple jump, pole vault
- 2x high jump
- 1x: shot put, discus, hammer, javelin

## FACILITY CONDITION - shortcomings:

- dilapidated, cracked and bubbly synthetic surface, multiple offset points
- poorly visible floor markings
- electrical and electronic connections are worn out
- oversized throwing sector by 20 cm
- no curb on the stadium's northern semicircle
- arrange conditions for placing a fotofinish video camera on the cabin
- protective construction for the discus and hammer throw does not meet the rules
- water jump barrier does not comply with the rules
- renovation of the shot put area needed
- there are no starting marks and obstacle marks on the inner curb in final straight

## EQUIPMENT CONDITION – what is missing?

- steeplechase hurdles are damaged
- replace the synthetic liner on the starter block supports
- cart for hurdles carriage
- stands for hammers and javelins

## OBJECTIVES

The priorities are as follows:

- renovation of synthetic surface of the venue
- renovation of the stands based on the building permit obtained
- landscaping of the auxiliary throwing site

## SUITABLE FOR RANK OF COMPETITIONS:

- all competitions

## OBJECT RANK: A



# VELENJE

## GENERAL INFORMATION:

**Venue name:** Velenje city stadium

**Operator:** HTZ IP d.o.o. Velenje

**Built:** 1994

**Capacity:** 1200 seated, 2000 standing

**Certification:** 2006, 2009, 2014

## FACILITY:

Surface: B-M, 7.600 m<sup>2</sup>

- 8 lines / 400m
- 1x: long jump, triple jump, pole vault, high jump
- 1x: shot put, discus, hammer, javelin

## FACILITY CONDITION - shortcomings:

- 400m track is outside the permissible standard (it is too long)
- the synthetic surface is worn out and damaged in several places
- floor markings are not visible enough
- there is no inner curb in the southern semicircle
- no auxiliary athletic facility

## EQUIPMENT CONDITION – what is missing?

- discus, hammers, javelins of different weights

## OBJECTIVES

The priorities are as follows:

- renovation of synthetic surface of the venue and floor markings
- purchase of big screen for viewers
- purchase of pole vault equipment (stands, mats ...)
- purchase of steeplechase hurdles
- renovation of electrical and electronic connections
- new measurements of the venue according to IAAF standards

## SUITABLE FOR RANK OF COMPETITIONS:

- all competitions

**OBJECT RANK: A**



# PTUJ

## GENERAL INFORMATION:

**Venue name:** Ptuj city stadium

**Operator:** Zavod za šport Ptuj

**Built:** 2004, renovation of synthetic surface 2015

**Capacity:** 949 seated (covered) and 657 seated (uncovered), 500 standing

**Certification:** 2006, 2009, 2014

## FACILITY:

Surface: spurtan WS 13, 5.690 m<sup>2</sup>

- 6 lines / 400m
- 1x: long jump, triple jump, pole vault, high jump
- 1x: shot put, discus, hammer, javelin

## FACILITY CONDITION - shortcomings:

- protective construction for the discus and hammer throw does not meet the rules
- there is no inner curb on the both semicircles of the stadium
- there are no electrical installations inside the competition sites

*The finish line is located on the south side of the property, opposite the main grandstand!*

## EQUIPMENT CONDITION – what is missing?

- no stands for discus, hammers, shot put
- no starting cart

## OBJECTIVES

The priorities are as follows:

- arrangement of the protective construction for the hammer throw according to the rules
- making of new runway for the javelin throw on the west side of the stadium

## SUITABLE FOR RANK OF COMPETITIONS:

- all competitions (except from senior national championships and senior national cup)

## OBJECT RANK: B





# NOVO MESTO

## GENERAL INFORMATION:

**Venue name:** Stadium Portoval Novo mesto

**Operator:** Agencija za šport Novo mesto

**Built:** 1981, renovated 2003

**Capacity:** 420 seated, 1000 standing

**Certification:** 2009, 2014

## FACILITY:

Surface: Conipur SP, 8.000 m<sup>2</sup>

- 8 lines / 400m
- 2x: long jump, triple jump
- 1x: pole vault, high jump
- 1x: shot put, discus, hammer, javelin

## FACILITY CONDITION:

- new venue which is IAAF rules compliant
- venue is IAAF certified (rank 2)

## FACILITY CONDITION - shortcomings:

- football goals cannot be removed

## EQUIPMENT CONDITION – what is missing?

- 230 V internal cable connections and computer connections

## OBJECTIVES

The priorities are as follows:

- construction of a hall with a 200 m circular track

## SUITABLE FOR RANK OF COMPETITIONS:

- all competitions

## OBJECT RANK: A



# NOVA GORICA

## GENERAL INFORMATION:

**Venue name:** Sport Park Nova Gorica

**Operator:** Javni zavod za šport Nova Gorica

**Built:** 1974, renovated 1994, 2000 and 2010

**Capacity:** 2200 seated, 1000 standing

**Certification:** 2007, 2010, 2014

## FACILITY:

Surface: B-M, 7.500 m<sup>2</sup>

- 8 lines / 400m
- 1x: long jump, triple jump
- 1x: pole vault, high jump
- 1x: shot put, javelin

## FACILITY CONDITION - shortcomings:

- there is no inner curb on the southern and northern semicircles of the stadium
- no electrical and computer connection between the finish and the measurement team site

## OBJECTIVES

The priorities are as follows:

- installation of inner curb
- to build a discus and hammer throwing facility

## OBJECT RANK: A





# DOMŽALE

## GENERAL INFORMATION:

**Venue name:** Sport Park Domžale

**Operator:** Zavod za šport in rekreacijo Domžale

**Built:** 2006

**Capacity:** 3000 seated

**Certification:** 2009, 2011, 2014

## FACILITY:

Surface: polytan WS, 5.076 m<sup>2</sup>

- 6 lines / 400m, 8 lines / 100m
- 2x: long jump, triple jump
- 1x: pole vault, high jump
- 1x: shot put, javelin, discus
- 1x: discus and hammer on auxiliary site

## FACILITY CONDITION - shortcomings:

- 7th and 8th line do not have a long enough run-out due to the metal fence (danger to competitors)
- there is no inner curb in the southern semicircle; some severely damaged curbs (urgent replacement)
- the opening on the protective structure of the discus and hammer throwing site in the auxiliary stadium is too large and does not meet the competition rules
- unable to have discus and pole vault competition simultaneously
- endangering security on ancillary football pitch in discus and hammer throw site - urgent need to put safety fence next to right sector

## EQUIPMENT CONDITION – what is missing?

- protective construction with a safety net for hammer throwing at the main stadium

## OBJECTIVES


The priorities are as follows:

- the layout of competition sites is unusual for organizing competitions, we suggest that the long jump and triple jump facility is moved the east side of the venue in front of the tribune

## SUITABLE FOR RANK OF COMPETITIONS:

- all competitions (except from senior national championships and senior national cup)

## OBJECT RANK: B





# KOČEVJE

## GENERAL INFORMATION:

**Venue name:** Stadium ob Rinži

**Operator:** Športna zveza Kočevje

**Built:** 1977, renovated 2001

**Capacity:** 1000 seated, 1000 standing

**Certification:** /

## FACILITY:

Surface: polytan WS, 4.600 m<sup>2</sup>

- 6 lines / 400m
- 1x: long jump, triple jump, high jump
- 1x: shot put, javelin,

## FACILITY CONDITION - shortcomings:

- there is no pole vault facility
- there is no discus and hammer throw facility
- no infrastructure for electronic measurements
- no additional sites (office, speaker, press, medical ...)

## EQUIPMENT CONDITION – what is missing?

- most of the equipment

## OBJECTIVES

The priorities are as follows:

- additional competition facilities
- activate work of local athletic club

## SUITABLE FOR RANK OF COMPETITIONS:

- meetings
- school competitions

## OBJECT RANK: C



# POSTOJNA

## GENERAL INFORMATION:

**Venue name:** Municipality sport park Postojna

**Operator:** Športna zveza Postojna

**Built:** 1978, renovated 2005

**Capacity:** 1200 standing

**Certification:** 2009, 2014

## FACILITY:

Surface: polytan WS 13, 5.100 m2

- 6 lines / 400m
- 2x: long jump, triple jump
- 1x: high jump, pole vault
- 1x: shot put, javelin,



## FACILITY CONDITION - shortcomings:

- there is no inner curb in both semicircles
- no start markings on the floor and markings for hurdles
- there is no pole vault facility
- no electric installations
- no infrastructure for electronic measurements
- no protective construction and safety net on the discus and hammer throw site
- take-off boards need renovation

## EQUIPMENT CONDITION – what is missing?

- steeplechase hurdles are rules not compliant
- starting cart and stand for judges at the finish line
- marks for length of the jumps for the viewers
- discuss, hammers and javelins of different weights
- no stands for discuss, hammers and javelins

## OBJECTIVES

The priorities are as follows:

- to buy equipment and make facilities for pole vault, discus and hammer
- installation of electronic measurement infrastructure on the stands
- installation of curbs
- purchase of missing equipment (hurdles, discuss, hammers ...)

## SUITABLE FOR RANK OF COMPETITIONS:

- national championships U12 and U14
- meetings
- school competitions

**OBJECT RANK: C**

# RAVNE NA KOROŠKEM

## GENERAL INFORMATION:

**Venue name:** Stadium in sport park Ravne

**Operator:** Zavod za kulturo, šport, turizem in mladinske dejavnosti Ravne

**Built:** 1997, renovated 2009

**Capacity:** 360 seated, 1000 standing

**Certification:** 2006, 2009, 2014

## FACILITY:

Surface: polytan WS, 5.900 m<sup>2</sup>

- 6 lines / 400m
- 2x: long jump, triple jump
- 1x: high jump
- 2x: pole vault
- 1x: shot put, javelin, discus, hammer



## FACILITY CONDITION - shortcomings:

- there is no inner curbs
- no electric installations on the venue
- protective construction and safety net on the discus and hammer throw site is not rules compliant
- take-off boards are inappropriate
- steeple chase hurdle are inappropriate

## EQUIPMENT CONDITION – what is missing?

- starting cart

## OBJECTIVES

The priorities are as follows:

- installation of inner curbs
- arrangement of protective construction and safety net on the discus and hammer throw site
- football goal must be made movable during athletic competitions

## SUITABLE FOR RANK OF COMPETITIONS:

- all competitions (except from senior national championships and senior national cup)

## OBJECT RANK: B

# BREŽICE

## GENERAL INFORMATION:

**Venue name:** Athletic stadium Brežice

**Operator:** Zavod za šport Brežice

**Built:** 1999

**Capacity:** 360 seated, 1000 standing

**Certification:** 2006, 2009, 2014

## FACILITY:

Surface: polytan WS, 6.900 m<sup>2</sup>

- 6 lines / 400m
- 1x: long jump, triple jump, high jump, pole vault
- 2x: shot put
- 1x: javelin, discus, hammer



## FACILITY CONDITION - shortcomings:

- worn out and damaged synthetic surface
- there is no inner curb in both semicircles, curbs are damaged
- no electric installations on the venue
- no electronic measurement conditions
- protective construction and safety net on the discus and hammer throw site is damaged
- no additional sites (office, speaker, press, medical ...)

## EQUIPMENT CONDITION – what is missing?

- stands for judges at finish area
- steeplechase hurdles
- starting cart
- cart for transport of hurdles
- length marks at long jump site
- stands for shot put, javelin, discus and hammer

## OBJECTIVES

The priorities are as follows:

- documentation for finishing the venue
- renovate the synthetic surface
- arrangement of protective construction and safety net on the discus and hammer throw site

## SUITABLE FOR RANK OF COMPETITIONS:

- all competitions (except from senior national championships and senior national cup)

**OBJECT RANK: B**

# SLOVENJ GRADEC

## GENERAL INFORMATION:

**Venue name:** sport center Vinko Cajnko Slovenj Gradec

**Operator:** Spotur - Javni zavod za turizem in šport Slovenj Gradec

**Built:** 2011

**Capacity:** 1000 seated, 200 standing

**Certification:** 2011, 2014

## FACILITY:

Surface: polytan M, 6.792 m<sup>2</sup>

- 6 lines / 400m; 8 lines / 100m
- 1x: long jump, triple jump, high jump, pole vault
- 1x: shot put, javelin, discus, hammer

## FACILITY CONDITION - shortcomings:

- throwing sector is too high (20-35 cm)
- some markings before water jump are missing

## OBJECTIVES

The priorities are as follows:

- lowering the grass area at throwing site for 25-30 cm that the throwing sector will be rules compliant

## SUITABLE FOR RANK OF COMPETITIONS:

- all competitions (except from senior national championships and senior national cup)

## OBJECT RANK: B



# SLOVENSKA BISTRICA

## GENERAL INFORMATION:

**Venue name:** sport park Slovenska Bistrica  
**Operator:** Zavod za šport Slovenska Bistrica  
**Built:** 1999, renovated 2009  
**Capacity:** 984 seated, 1000 standing  
**Certification:** 2006, 2009, 2014

## FACILITY:

Surface: polytan WS, 5.650 m<sup>2</sup>

- 6 lines / 400m
- 1x: long jump, triple jump, high jump, pole vault
- 1x: shot put, javelin, discus, hammer

## FACILITY CONDITION - shortcomings:

- no electric installations on the venue
- no pole vault facility
- take-off board's covers need a replacement
- arrangement of the base for opening and closing the doors of the protective structure

## EQUIPMENT CONDITION – what is missing?

- steeplechase hurdles
- length marks at triple jump site
- hammers (different weights)
- stands for javelin, discus and hammer
- control kit for shot put, javelin, hammer, discus
- start cart and stands for judges at finish area

## OBJECTIVES

The priorities are as follows:

- illumination of the venue
- to build additional shot put facility for training sessions
- installation of electric connection
- renovation of pole vault facility
- reconstruction of hammer throw protective construction

## SUITABLE FOR RANK OF COMPETITIONS:

- national championships U12 and U14
- meetings
- school competitions

**OBJECT RANK: B**





# RADOVLJICA

## GENERAL INFORMATION:

**Venue name:** Athletic Park at OŠ AntonaTomaža Linhartaradovljica

**Operator:** Radovljica Municipality

**Built:** 2010, renovated 2015 (synthetic surface)

**Certification:** 2016

## FACILITY:

Surface: Conipur SP, 5.800 m<sup>2</sup>

- 6 lines / 400m
- 1x: long jump, triple jump, high jump
- 1x: shot put, javelin, discus, hammer

## FACILITY CONDITION - shortcomings:

- no electric installations on the venue
- no pole vault facility
- no electronic measurement conditions
- renovation of shot put facility
- runway for javelin throw on the east side of the venue
- renovation of the surface at high jump site
- there is no additional sites (offices, speaker, press, medical ...)

## EQUIPMENT CONDITION – what is missing?

- there is a need for additional equipment

## OBJECTIVES

The priorities are as follows:

- arrangement of missing competition sites
- purchase of new/missing equipment

## SUITABLE FOR RANK OF COMPETITIONS:

- national championships U12 and U14 (heptathlon, pentathlon ...)
- meetings
- school competitions

## OBJECT RANK: C



# ČRNOMELJ

## GENERAL INFORMATION:

**Venue name:** Stadium Loka

**Operator:** Športna zveza Črnomelj

**Built:** 2001

**Capacity:** 650 seated, 1000 standing

**Certification:** /

## FACILITY:

Surface: polytan WS, 3.900 m<sup>2</sup>

- 4 lines / 400m; 6 lines /100m
- 1x: long jump, triple jump, high jump
- 1x: shot put, javelin

## FACILITY CONDITION - shortcomings:

- no electric installations on the venue
- no pole vault facility
- no hammer and discus throw facility
- no electronic measurement conditions
- there is no additional sites (offices, speaker, press, medical ...)

## EQUIPMENT CONDITION – what is missing?

- there is a need for additional equipment

## OBJECTIVES

The priorities are as follows:

- arrangement of missing competition sites
- activate local athletic club

## SUITABLE FOR RANK OF COMPETITIONS:

- meetings
- school competitions

## OBJECT RANK: C



# BLED

## GENERAL INFORMATION:

**Venue name:** Sport Park Bled

**Operator:** AD Bled in NK Bled

**Built:** 2006

**Capacity:** 2000 standing

**Certification:** 2009, 2014



## FACILITY:

Surface: polytan WS, 5.055 m2

- 6 lines /400m
- 1x: long jump, triple jump, high jump, pole vault
- 1x: shot put, javelin, hammer, discus

## FACILITY CONDITION - shortcomings:

- water jump on the wrong place
- no electronic measurement conditions
- no electric connections
- door at hammer throw site does not open/close
- there are no start marks for 100 and 110 hurdles
- badly maintained synthetic surface

## EQUIPMENT CONDITION – what is missing?

- there is a need for additional equipment
- no start cart and no judge stands at finish line

## OBJECTIVES

The priorities are as follows:

- wrongly placed water jump does not allow to organize national championships
- Along the landing area of long and triple jump the fence must be relocated (0,5m) for the athlete's safety.

## SUITABLE FOR RANK OF COMPETITIONS:

- national championships U12, U14 and U16 under condition that the hammer throw site is being modified
- meetings
- school competitions

## OBJECT RANK: C



# ŽALEC

## GENERAL INFORMATION:

**Venue name:** Sport Centre Žalec

**Operator:** Zavod za kulturo, šport in turizem Žalec

**Built:** 2002

**Capacity:** 250 seated, 300 standing

**Certification:** 2009, 2014



## FACILITY:

Surface: polytan WS, 5.814 m<sup>2</sup>

- 6 lines /400m; 8 lines /100m
- 1x: long jump, triple jump, high jump, pole vault
- 1x: shot put, javelin

## FACILITY CONDITION - shortcomings:

- no inner curbs on both semicircles
- no electronic measurement conditions
- no electric connections
- there is no additional sites (offices, speaker, press, medical ...)

## EQUIPMENT CONDITION – what is missing?

- steeplechase hurdles
- equipment for pole vault (sands, bars, mats)
- stopping area is not rules compliant
- protective construction for hammer and discus throw
- shot put boxes with metric marks
- scoreboards (discus, hammer, javelin)
- discuss, javelins, shot puts of various weights

## OBJECTIVES

The priorities are as follows:

- installation of electric and electronic connections
- additional sites
- installation of missing curbs
- purchase of steeplechase hurdles
- purchase of pole vault equipment
- new mat cover for high jump
- purchase of protective construction for hammer and discus throw
- new circle for hammer and discus throw
- new take-off boards with plasticine

## SUITABLE FOR RANK OF COMPETITIONS:

- national championships U12, U14
- meetings
- school competitions

**OBJECT RANK: C**

# ŠENTJUR

## GENERAL INFORMATION:

**Venue name:** Stadium Šentjur

**Operator:** Šentjur Municipality

**Built:** 2004

**Certification:** 2011, 2014

## FACILITY:

Surface: polytan WS, 4.172 m<sup>2</sup>

- 4 lines /400m; 6 lines /100m
- 1x: long jump, triple jump, high jump
- 1x: shot put, javelin

## FACILITY CONDITION - shortcomings:

- no pole vault facility
- no discus and hammer facility
- no electronic measurement conditions
- no electric connections
- there is no additional sites for organizing competitions

## EQUIPMENT CONDITION – what is missing?

- insufficient equipment

## OBJECTIVES

The priorities are as follows:

- extension of line 5 and 6 according to the rules
- arrangement of missing facilities
- purchase of throwing equipment for all categories

## SUITABLE FOR RANK OF COMPETITIONS:

- meetings
- school competitions

## OBJECT RANK: C



# LJUBLJANA

## GENERAL INFORMATION:

**Venue name:** Sport Park Kodeljevo

**Operator:** Javni zavod Šport Ljubljana

**Built:** 1994

**Capacity:** 500 seated, 1500 standing

**Certification:** 2011, 2014



## FACILITY:

Surface: polytan WS, 4.600 m<sup>2</sup>

- 6 lines /400m;
- 1x: long jump, triple jump, high jump

## FACILITY CONDITION - shortcomings:

- no steeplechase equipment (hurdles, water jump)
- no pole vault and triple jump facility
- no throwing facilities
- long jump and high jump facilities are useless
- worn out synthetic surface
- no electronic measurement conditions
- no electric connections
- there is no additional sites for organizing competitions
- missing floor markings

## EQUIPMENT CONDITION – what is missing?

- there is no equipment

## OBJECTIVES

The priorities are as follows:

- renovation of the synthetic surface
- add steeplechase equipment
- add long jump, triple jump and pole vault facility
- add all the throwing sites
- purchase of all the equipment

## SUITABLE FOR RANK OF COMPETITIONS:

- none

**OBJECT RANK:** /



# LJUBLJANA

## GENERAL INFORMATION:

**Venue name:** Stadium Tacen

**Operator:** Ministry of the Interior

**Built:** 1990

**Certification:** /



## FACILITY:

Surface: polytan WS, 3.962 m<sup>2</sup>

- 4 lines /400m; 6 lines /100m
- 1x: long jump, triple jump, high jump
- 2x: shot put
- 1x: javelin

## FACILITY CONDITION - shortcomings:

- no discus and hammer throwing facilities
- no electronic measurement conditions
- no electric connections
- there is no additional sites for organizing competitions

## EQUIPMENT CONDITION – what is missing?

- lack of equipment

## OBJECTIVES

The priorities are as follows:

- priorities are determined by Ministry of the Interior

## SUITABLE FOR RANK OF COMPETITIONS:

- meetings
- school competitions

## OBJECT RANK: C





# TOLMIN

## GENERAL INFORMATION:

**Venue name:** Stadium na Brajdi

**Operator:** Zavod za šport Tolmin

**Built:** 1982

**Certification:** /

## FACILITY:

Surface: /

- 6 lines /400m;

## FACILITY CONDITION - shortcomings:

- stadium is not appropriate for any competition

## EQUIPMENT CONDITION – what is missing?

- lack of equipment

## OBJECTIVES

The priorities are as follows:

- general renovation

## SUITABLE FOR RANK OF COMPETITIONS:

- none

**OBJECT RANK:** no competition is allowed



# KAMNIK

## GENERAL INFORMATION:

**Venue name:** Stadium of friendship in Mekinje (Kamnik)

**Operator:** Zavod za turizem in šport Kamnik

**Built:** 2014

**Certification:** /

## FACILITY:

Surface: polytan M, 3.100 m<sup>2</sup>

- 6 lines /400m;

## FACILITY CONDITION:

- track is finished, as well as long jump, triple jump and high jump facilities
- other facilities will be finished in next few years



# ATHLETIC INDOOR FACILITIES IN SLOVENIA

## LJUBLJANA

### GENERAL INFORMATION:

**Venue name:** Sport Park Ljubljana

**Operator:** Javni zavod Šport Ljubljana

**Built:** 1990, renovated 1999

**Certification:** 2006, 2009, 2014

### FACILITY:

Surface: polytan Retopping SE, 1.822 m<sup>2</sup>

- 6 lines /60 m, 60 m hurdles;
- 1x: long jump, triple jump, high jump, pole vault



# CELJE

## GENERAL INFORMATION:

**Venue name:** Athletic hall Kladivar

**Operator:** AD Kladivar Celje

**Built:** 1964, renovated 1976, 1991 and 2000

**Certification:** 2006, 2009, 2014

## FACILITY:

Surface: polytan M, 822 m<sup>2</sup> and polytan Retopping, 822 m<sup>2</sup>

- 6 lines /60 m, 60 m hurdles;
- 1x: long jump, triple jump, high jump, pole vault



# ŠEMPETER PRI GORICI

## GENERAL INFORMATION:

**Venue name:** HIT Sport Centre Nova Gorica

**Operator:** HIT d.d., Nova Gorica

**Built:** 1997

**Certification:** 2007

## FACILITY:

Surface: Mondo, 1.680 m<sup>2</sup>

- 6 lines /60 m, 60 m hurdles;
- 1x: long jump, triple jump, pole vault



# SLOVENSKA BISTRICA

## GENERAL INFORMATION:

**Venue name:** Sport Park Slovenska Bistrica

**Operator:** Zavod za šport Slovenska Bistrica

**Built:** 2005, renovated 2009

**Certification:** 2009, 2014

## FACILITY:

Surface: polytan WS, 1.000 m<sup>2</sup>

- 5 lines /60 m, 60 m hurdles;
- 1x: long jump, triple jump, high jump, pole vault
- 1x: shot put



# PTUJ

## GENERAL INFORMATION:

**Venue name:** City Stadium Ptuj

**Operator:** Zavod za šport Ptuj

**Built:** 2005

**Certification:** 2006, 2009, 2014

## FACILITY:

Surface: spurtan WS 13, 500 m<sup>2</sup>

- 3 lines /60 m, 60 m hurdles;
- 1x: long jump



# Athletic school facilities in Slovenia

## LENDAVA

### GENERAL INFORMATION:

**Venue name:** Sport Park Lendava

**Built:** 2009

### FACILITY:

Surface: polytan WS 13, 3.960 m<sup>2</sup>

- 4 lines /400m;
- 1x: long jump, high jump
- 1x: shot put

### FACILITY CONDITION:

- no discus, hammer, javelin, pole vault and triple jump facilities
- no inner curb
- no water jump





# MURSKA SOBOTA

## GENERAL INFORMATION:

**Venue name:** Athletic Stadium at I. Murska Sobota Elementary School

## FACILITY:

Surface: polytan WS, 3.960 m<sup>2</sup>

- 4 lines /300m; 6 lines /100m
- 2x: long jump, triple jump
- 1x: high jump, pole vault
- 1x: shot put, javelin

## FACILITY CONDITION:

- no discus, hammer facilities
- no water jump



# ŠENTJERNEJ

## GENERAL INFORMATION:

**Venue name:** Athletic Stadium at Šentjernej Elementary School

## FACILITY:

Surface: polytan WS, 3.029 m<sup>2</sup>

- 4 lines /300m; 6 lines /100m
- 1x: long jump, triple jump, high jump
- 1x: shot put, javelin

## FACILITY CONDITION:

- no discus, hammer and pole vault facilities
- no water jump



# ORMOŽ

## GENERAL INFORMATION:

Venue name: Sport Park Ormož

## FACILITY:

Surface: polytan WS, 4.050 m<sup>2</sup>

- 6 lines /300m;
- 1x: long jump, triple jump, high jump
- 1x: shot put, javelin

## FACILITY CONDITION:

- no discus, hammer and pole vault facilities
- no water jump



# SEŽANA

## GENERAL INFORMATION:

Venue name: Sport Park Sežana

## FACILITY:

Surface: polytan WS, 1.934 m<sup>2</sup>

- 4 lines /300m;
- 1x: long jump, triple jump, high jump
- 1x: shot put

## FACILITY CONDITION:

- no discus, hammer, javelin and pole vault facilities
- no water jump



# LJUBLJANA

## GENERAL INFORMATION:

Venue name: Tivoli exercise area

## FACILITY:

Surface: polytan WS, 1.100 m<sup>2</sup>

- 4 lines /326,4 m; 6 lines /100 m
- 1x: long jump, high jump
- 1x: shot put, javelin

## FACILITY CONDITION:

- no discus, hammer, triple jump and pole vault facilities
- no water jump



# BLED

## GENERAL INFORMATION:

**Venue name:** Sport Park at Bled Elementary School – Plemelj

**Built:** 2014

## FACILITY:

Surface: polytan WS, 2.400 m<sup>2</sup>

- 4 lines /200 m; 4 lines /60 m
- 1x: long jump, high jump
- 1x: shot put

# BISTRICA OB SOTLI

## GENERAL INFORMATION:

**Venue name:** Sport Park at Elementary School

**Built:** 2004

## FACILITY:

Surface: polytan WS, 1.400 m<sup>2</sup>

- 4 lines /200 m
- 1x: long jump



# BISTRICA PRI TRŽIČU

## GENERAL INFORMATION:

**Venue name:** Sport Park at Elementary School OŠ Bistrica

**Built:** 2013

## FACILITY:

Surface: polytan WS, 1.177 m<sup>2</sup>

- 4 lines /200 m
- 1x: long jump



# BOGOJINA

## GENERAL INFORMATION:

**Venue name:** Sport Park at Elementary School

**Built:** 2008

## FACILITY:

Surface: polytan WS, 214 m<sup>2</sup>

- 4 lines /60 m
- 1x: long jump



# BOHINJSKA BISTRICA

## GENERAL INFORMATION:

**Venue name:** Sport Park at Elementary School

**Built:** 2009

## FACILITY:

Surface: polytan WS, 1.298 m<sup>2</sup>

- 200 m track



# BOVEC

## GENERAL INFORMATION:

**Venue name:** Sport Park at Elementary School

**Built:** 2004

## FACILITY:

Surface: polytan WS

- 6 lines / 80m
- 1x: long jump

# CELJE

## GENERAL INFORMATION:

**Venue name:** Sport Park at IV. Elementary School

**Built:** 2006

## FACILITY:

Surface: polytan WS, 944 m<sup>2</sup>

- 4 lines / 200 m
- 1x: long jump, shot put

# CELJE

## GENERAL INFORMATION:

**Venue name:** Sport Park at I. gymnasium

**Built:** 2010

## FACILITY:

Surface: polytan WS, 2.795 m<sup>2</sup>

- track 200 m
- 1x: long jump, high jump, shot put

# DOBROVA PRI LJUBLJANI

## GENERAL INFORMATION:

**Venue name:** Sport Park at Elementary School

**Built:** 2010

## FACILITY:

Surface: polytan WS, 728 m<sup>2</sup>

- 2 lines/200 m; 4 lines /60m
- 1x: long jump



# DRAGOMELJ

## GENERAL INFORMATION:

**Venue name:** Sport Park at Elementary School

**Built:** 2006

## FACILITY:

Surface: 410 m<sup>2</sup>

- 4 lines /100m
- 1x: long jump, shot put

# GORNJA RADGONA

## GENERAL INFORMATION:

Venue name: Sport Park at Elementary School

Built: 2011

## FACILITY:

Surface: polytan WS

- 4 lines /100m
- 1x: long jump, shot put



# GRIŽE

## GENERAL INFORMATION:

**Venue name:** Sport Park at Elementary School

**Built:** 2011

## FACILITY:

Surface: polytan WS

- 2 lines /200m; 4 lines/100m
- 1x: long jump, high jump

# GROSUPLJE

## GENERAL INFORMATION:

**Venue name:** Athletic Stadium at OŠ Brinje

## FACILITY:

- 4 lines/200m; 4 lines/60m
- 1x: long jump, triple jump



# IZLAKE

## GENERAL INFORMATION:

Venue name: Sport Park Izlake

Built: 2007

## FACILITY:

Surface: polytan WS

- 2 lines /300m; 4 lines/60m
- 1x: long jump, shot put



# JESENICE

## GENERAL INFORMATION:

Venue name: Sport Park OŠ Prežihov Voranc

## FACILITY:

Surface:

- 2 lines /200m;
- 1x: long jump, high jump, shot put

# KIDRIČEVO

## GENERAL INFORMATION:

Venue name: Sport Park at Elementary School

## FACILITY:

Surface: polytan WS

- 4 lines /100m;

# KOČEVJE

## GENERAL INFORMATION:

Venue name: Sport Park at Elementary School

## FACILITY:

Surface: polytan WS

- 2 lines /150m;
- 1x: long jump

# KOPER

## GENERAL INFORMATION:


Venue name: Sport Park at OŠ Koper

Built: 2006

## FACILITY:

Surface: 564 m<sup>2</sup>

- 6 lines /80m;
- 1x: long jump



# KRANJ

## GENERAL INFORMATION:

**Venue name:** Sport Park at Srednja ekonomska gimnazija

**Built:** 2007

## FACILITY:

Surface: 1.204 m<sup>2</sup>

- 4 lines /100 m;
- 1x: long jump, shot put

# KRŠKO

## GENERAL INFORMATION:

**Venue name:** Sport Park at OŠ Jurija Dalmatina

**Built:** 2010

## FACILITY:

Surface: polytan WS, 1.202 m<sup>2</sup>

- 200 m track;
- 1x: long jump, high jump, shot put

# KRIŽE

## GENERAL INFORMATION:

**Venue name:** Sport Park at Elementary School

**Built:** 2011

## FACILITY:

Surface: polytan WS

- 3 lines/200 m; 4 lines/80m
- 1x: long jump, high jump



# LESCE

## GENERAL INFORMATION:

**Venue name:** Sport Park at Elementary School F.S. Finžgar

**Built:** 2011

## FACILITY:

Surface: polytan WS, 4.609 m<sup>2</sup>

- 4 lines/200 m;
- 1x: long jump, high jump, shot put



# LIPNICA

## GENERAL INFORMATION:

**Venue name:** Sport Park at Elementary School Stane Žagar

**Built:** 2009

## FACILITY:

Surface: polytan WS, 1.819 m<sup>2</sup>

- 250 m track



# LJUBEČNA

## GENERAL INFORMATION:

**Venue name:** Sport Park at Elementary School

## FACILITY:

Surface:

- 2 lines/200 m;

# LOGATEC

## GENERAL INFORMATION:

**Venue name:** Sport Park at Elementary School 8. talcev

## FACILITY:

Surface:

- 4 lines/160 m;
- 1x: long jump, high jump

# LJUBJANA

## GENERAL INFORMATION:

**Venue name:** Sport site Poljane at Srednja trgovska šola

**Built:** 2007

## FACILITY:

Surface: polytan WS, 650 m<sup>2</sup>

- 4 lines/300 m; 4 lines/100m
- 1x: long jump, high jump, shot put

# LJUBJANA

## GENERAL INFORMATION:

**Venue name:** Sport park at OŠ Miška Kranjca

**Built:** 2005

## FACILITY:

Surface: polytan WS, 600 m<sup>2</sup>

- 2 lines/200 m; 4 lines/100m
- 1x: long jump

# LJUBJANA

## GENERAL INFORMATION:

Venue name: Sport park at OŠ Bičevje

Built: 2004

## FACILITY:

Surface: polytan WS, 387 m<sup>2</sup>

- 3 lines/80 m
- 1x: shot put

# LJUBJANA

## GENERAL INFORMATION:

Venue name: Sport Park at OŠ Hinko Smrekar

## FACILITY:

Surface:

- 2 lines/200 m



# LJUBJANA

## GENERAL INFORMATION:

Venue name: Sport Park at OŠ Koseze

Built: 2007

## FACILITY:

Surface: polytan WS, 928 m<sup>2</sup>

- 4 lines/150 m



# LJUBJANA

## GENERAL INFORMATION:

Venue name: Sport Park at OŠ Nove Jarše

Built: 2008

## FACILITY:

Surface: polytan WS, 560 m<sup>2</sup>

- 2 lines/150 m
- 1x: long jump, high jump, shot put

# LJUBJANA

## GENERAL INFORMATION:

**Venue name:** Sport Park at Gimnazija Šentvid

**Built:** 2005

## FACILITY:

Surface: polytan WS, 1.152 m<sup>2</sup>

- 4 lines/200 m
- 1x: long jump, high jump, shot put



# LJUBJANA

## GENERAL INFORMATION:

**Venue name:** Sport Park at OŠ Sostro

**Built:** 2004

## FACILITY:

Surface: polytan WS, 621 m<sup>2</sup>

- 3 lines/60 m

# LJUBJANA

**GENERAL INFORMATION:**

**Venue name:** Sport Park at OŠ Polje

**Built:** 2014

**FACILITY:**

Surface: polytan WS, 2.400 m<sup>2</sup>

- 3 lines/200 m; 3 lines / 60 m
- 1x: long jump

# LJUBJANA

**GENERAL INFORMATION:**

**Venue name:** Sport Park at OŠ Kašelj

**Built:** 2014

**FACILITY:**

Surface: polytan WS, 1.016 m<sup>2</sup>

- 3 lines/150 m; 3 lines / 60m
- 1x: long jump, high jump

# MARIBOR

**GENERAL INFORMATION:**

**Venue name:** Sport Park at OŠ Angela Besednjak

**Built:** 2009

**FACILITY:**

Surface: polytan WS, 1.600 m<sup>2</sup>

- 4 lines/80m

# MARIBOR

**GENERAL INFORMATION:**

**Venue name:** Sport Park at OŠ Franc Rozman Stane

**Built:** 2007

**FACILITY:**

Surface: polytan WS, 750 m<sup>2</sup>

- 4 lines/200m
- 1x: long jump, high jump, shot put

# MARIBOR

## GENERAL INFORMATION:

**Venue name:** Sport Park at OŠ Draga Kobala

**Built:** 2004

## FACILITY:

Surface: polytan WS, 1.156 m<sup>2</sup>

- 4 lines/200m
- 1x: long jump

# MIKLAVŽ

## GENERAL INFORMATION:

**Venue name:** Sport Park at Elementary School

**Built:** 2008

## FACILITY:

Surface: polytan WS, 1.058 m<sup>2</sup>

- 4 lines/100m
- 1x: long jump; shot put

# MOKRONOG

## GENERAL INFORMATION:

**Venue name:** Sport Park at Elementary School

**Built:** 2011

## FACILITY:

Surface: polytan WS

- 4 lines/200m; 6 lines/100m
- 1x: long jump; high jump, shot put

# MURSKA SOBOTA

## GENERAL INFORMATION:

**Venue name:** Sport Park at Ekonomska srednja šola

**Built:** 2007

## FACILITY:

Surface: polytan WS, 1.477 m<sup>2</sup>

- 4 lines/200m;
- 1x: long jump; high jump, shot put

# MURSKA SOBOTA

## GENERAL INFORMATION:

**Venue name:** Sport Park at 2<sup>nd</sup> Elementary School

**Built:** 2007

## FACILITY:

Surface: polytan WS, 892 m<sup>2</sup>

- track 200m



# NAKLO

## GENERAL INFORMATION:


**Venue name:** Sport Park at OŠ Naklo

**Built:** 2005

## FACILITY:

Surface: polytan WS, 3.275 m<sup>2</sup>

- 4 lines/250m; 6 lines/100m
- 1x: long jump, triple jump, high jump, shotput, javelin



# PLANINA PRI SEVNICI

## GENERAL INFORMATION:

Venue name: Sport Park at Elementary School

Built: 2011

## FACILITY:

Surface: polytan WS, 1.446 m<sup>2</sup>

- 4 lines/200m;
- 1x: long jump, high jump, shotput

# PODBOČJE

## GENERAL INFORMATION:

Venue name: Sport Park at Elementary School

Built: 2007

## FACILITY:

Surface: polytan WS, 840 m<sup>2</sup>

- 3 lines/200m; 3 lines/80m
- 1x: long jump





# PODČETRTEK

## GENERAL INFORMATION:

**Venue name:** Athletic stadium Podčetrtek

**Built:** 2009

## FACILITY:

Surface: polytan WS, 3.381 m<sup>2</sup>

- 4 lines/345m; 6 lines/60m
- 1x: long jump, high jump, shot put



# POLZELA

## GENERAL INFORMATION:

**Venue name:** Sport and recreational park Polzela

**Built:** 2005

## FACILITY:

Surface: polytan WS, 1.180 m<sup>2</sup>

- 4 lines/300m
- 1x: long jump, high jump
- 1x: shot put



# PONIKVA

## GENERAL INFORMATION:

Venue name: Sport Park at OŠ Blaža Kocena Ponikva

Built: 2008

## FACILITY:

Surface: polytan WS, 544 m<sup>2</sup>

- 2 lines/200m; 4 lines/60m
- 1x: long jump, high jump



# POSTOJNA

## GENERAL INFORMATION:

Venue name: Sport Park at OŠ Anton Globočnik

Built: 2007

## FACILITY:

Surface: polytan WS, 300 m<sup>2</sup>

- 3 lines/60m



# PREDDVOR

## GENERAL INFORMATION:

Venue name: Sport Park at OŠ Matije Valjavca Preddvor

Built: 2007

## FACILITY:

Surface: polytan WS, 930 m<sup>2</sup>

- 4 lines/200 m
- 1x: long jump

# PTUJ

## GENERAL INFORMATION:

Venue name: Sport Park at SŠC Ptuj

## FACILITY:

Surface:

- 4 lines/250 m
- 1x: long jump, high jump, shot put

# ROGAŠKA SLATINA

## GENERAL INFORMATION:

Venue name: Sport Park at Elementary School

## FACILITY:

Surface:

- 2 lines/300 m; 4 lines/100m
- 1x: long jump, high jump, shot put

# SEČOVLJE

## GENERAL INFORMATION:

Venue name: Sport Park at Elementary School

## FACILITY:

Surface: polytan M, 1.740 m<sup>2</sup>

- 4 lines/200 m; 5 lines/100m
- 1x: long jump, high jump, shot put



# SLOVENSKE KONJICE

## GENERAL INFORMATION:

**Venue name:** Sport Park at OŠ Dravinja

**Built:** 2009

## FACILITY:

Surface: polytan WS, 1.909 m<sup>2</sup>

- 4 lines/200 m;
- 1x: long jump, high jump, shot put



# STARA CERKEV PRI KOČEVJU

## GENERAL INFORMATION:

**Venue name:** Sport Park at Elemetary School

## FACILITY:

Surface:

- 2 lines/200 m; 4 lines/100m
- 1x: long jump, shot put

# SVETA ANA V SLOVENSKIH GORICAH

## GENERAL INFORMATION:

Venue name: Sport Park at Elementary School

Built: 2009

## FACILITY:

Surface: polytan WS, 390 m<sup>2</sup>

- 4 lines/200m



# SVETI TOMAŽ PRI ORMOŽU

## GENERAL INFORMATION:

Venue name: Sport Park at Elementary School

Built: 2010

## FACILITY:

Surface: polytan WS, 1.007 m<sup>2</sup>

- 4 lines/200m

# ŠEMPETER PRI GORICI

## GENERAL INFORMATION:

Venue name: Sport Park at OŠ Ivana Roba

## FACILITY:

Surface:

- 4 lines/250m
- 1x: long jump, high jump, shot put



# ŠKOFJA LOKA

## GENERAL INFORMATION:

**Venue name:** Sport Park at OŠ Ivana Groharja

**Built:** 2001

## FACILITY:

Surface: polytan WS, 400 m<sup>2</sup>

- 4 lines/200m; 6 lines/100m
- 1x: long jump, high jump



# ŠMARJE PRI JELŠAH

## GENERAL INFORMATION:

**Venue name:** Sport Park at Elementary School

**Built:** 2006

## FACILITY:

Surface: polytan WS, 1.663 m<sup>2</sup>

- 4 lines/300m; 6 lines/100m
- 1x: long jump, high jump, shot put



# ŠOŠTANJ

## GENERAL INFORMATION:

**Venue name:** Sport Park at OŠ Ivana Groharja

**Built:** 2005

## FACILITY:

Surface: polytan WS, 2.110 m<sup>2</sup>

- 4 lines/200m;
- 1x: long jump, shot put

# TEPANJE

## GENERAL INFORMATION:

**Venue name:** Sport Park Tepanje

**Built:** 2007

## FACILITY:

Surface: polytan WS, 315 m<sup>2</sup>

- 4 lines/200m;

# TREBNJE

## GENERAL INFORMATION:

**Venue name:** Sport Park Trebnje

## FACILITY:

Surface:

- 5 lines/200m
- 1x: long jump

# TRZIN

## GENERAL INFORMATION:

**Venue name:** Sport and recreational park Trzin

**Built:** 2007

## FACILITY:

Surface: polytan WS, 1.881 m<sup>2</sup>

- 4 lines/300m; 6 lines/80m
- 1x: long jump, triple jump, high jump, pole vault
- 1x: shot put, discus, javelin



# VELIKA NEDELJA

## GENERAL INFORMATION:

**Venue name:** Sport Park at Elementary School

## FACILITY:

Surface:

- 4 lines/300m; 6 lines/100m
- 1x: long jump, triple jump, high jump, pole vault
- 1x: shot put, discus, javelin

# ŽELEZNIKI

## GENERAL INFORMATION:


**Venue name:** Sport Park at Elementary School

**Built:** 2010

## FACILITY:

Surface: polytan WS, 1.742 m<sup>2</sup>

- 4 lines/200m;
- 1x: long jump, high jump
- 1x: shot put



# ŽIROVNICA

## GENERAL INFORMATION:

**Venue name:** Sport Park at OŠ Zabreznica

**Built:** 2010

## FACILITY:

Surface: polytan WS, 887 m<sup>2</sup>

- track 200m
- 1x: long jump, high jump
- 1x: shot put

# CONCLUSION

Athletic facilities are, on average, old, but some have already been renovated and some require general renovation. Many activities in this case have already been done with the preparation of these document.

Unfortunately, we can still conclude that in 2016 we do not yet have an oval circular 200 m track in Slovenia. We hope that realization of this goal, hopefully in year 2018, will allow us to organize the first national championship in the roundabout arena.

